



1




Connect the wires to the power and mount the crossbar to the junction box.

2




Insert support screws into the slots and screw into the ceiling, securing the fixture firmly in place. Do not over-tight the screws.

3




Push the canopy on, and screw the end caps onto the nipples until the canopy is firmly secured.

4



Unscrew the end caps from the bottom of the pendants.

5



Slide the glass onto the hardware and screw on the end caps.

